














Technik F11 - Streichwachs transparent für C01, C02, C05, C06, B04, B51

	Produkt / Product / Produit / Prodotto	Werkzeug / Tool / Outil / Werktuig / Strumento	Aufbereitung / Preparation / Conditionnement / Toebereiding / Preparazione	Verbrauch / Use / Consommation / Verbruik / Consumo	Trocknung / Drying / Séchage / Droogtijd / Asciugatura			
1	FINALE		1 Ltr.  + 30 g FINALE	3 g / m ²	 5 - 10 min			
2	FINALE		1 Ltr.  + 30 g FINALE	3 g / m ²	 5 - 10 min			
3	FINO		2,1 Ltr.  + 700 g FINO (3:1)	30 - 40 g / m ²	 5 - 10 min			
4	FINO		2,1 Ltr.  + 700 g FINO (3:1)	30 - 40 g / m ²	 5 - 10 min			
5								
	trocken nachbürsten / dry brush / brosser sec / droog afborstelen / spazzola secco							